POPPLETON HISTORIC STUDY

mag1#0425365404

Block

Lot

Address

188

105-101

862-870 Vine Street

Approximate age

1800-1845

1845-1860

1865-1880

1880-1896

1896-on

(before 1852)

Ratin	Rating Architectural		<u>Condition</u>		
A	Significant-save	good	fair	poor	bad
В	quality-Indiv./groups-save	good	fair	poor	bad
(c)	Important to street/groups	good	fair	poor	bad
D	Insignificant/detrimental	good	fair	poor	bad

Notable features:

The row is among the earliest on the street and is composed of characteristic Vine Street houses.

Environmental context:


Number 870 is vacant. Vine is a narrow, quiet street but, in general, it is in poor condition with frequent demolition gaps. Scale is pleasant. Large gap east of this group from 846-860 and smaller one across street, 865-867.



Demolished


B-2536 862-870 Vine Street Block 188 Lot 101-105 Sanborn Map Baltimore 1890 vol. 3, Sheet 82_a

WEST LEXINGTON



WEST FAYETTE

B-2536 862-870 Vine Street Baltimore City



Demolished

B-2536 862-870 Vine Street Block 188 Lot 101-105 Baltimore City Baltimore West Quad.

